





EXISTING CONDITIONS




NOTE: MANY GAPS EXIST IN BRICK FACADE;  
 FILL WITH NEW BRICK OR SEALANT AS  
 NECESSARY TO PATCH FACADE



REMOVE EXISTING VINYL SIGNAGE  
 AND FORMER SIGN CONNECTIONS  
 ON FACADE



PAINTING INSTRUCTIONS



GENERAL NOTE: MANY GAPS EXIST IN BRICK WALL; THESE MUST BE PATCHED AND VERIFIED AS NON-STRUCTURAL OR PROBLEMATIC ISSUE

SIGN BOLTED TO FACADE (6'2" X 3'0"); CENTERED ABOVE DOOR WITH TOP EDGE OF SIGN ALIGNED WITH TOP OF WINDOW LINTELS

ELECTRICAL PANEL PAINTED BLACK

METAL PLANTERS INSTALLED AT LOWER-LEVEL WINDOW SILLS

ENTRYWAY PAINTED SW 6675 TO MATCH TRIM (WALLS OF ENCLOSED ENTRY AND STAIRS)

LOADING DOCK AREA CLEANED AND PAINTED WITH CHALKBOARD PAINT

FRONT FACADE DETAILS WITH PLANTERS





NOTES:  
 CENTERED LETTERING (HELVETICA)  
 RAISED BLACK PVC LETTERING - 1"  
 MATTE PAINT ON SIGN: R-251 G-203 B-120

TO BE CENTERED ABOVE DOOR  
 W/TOP OF FRAME LINED UP WITH TOP OF WINDOWS